

Work Order ID 88047

Wednesday, July 25, 2012 2:33:03 PM

88047

Page 1

Item ID: D4148-041

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Crosstube Lug Assembly, Fwd

Start Date: 7/24/2012 Start Qty: 2.00

2

Cust Item ID:

Required Date: 7/25/2012 Req'd Qty: 2.00

2

Customer: CU-DAR001

Reference: RMA RA111369 - RETURN

Approvals:

Process Plan: MVFDate: 12-07-25

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

Draw Nbr

Revision Nbr

D4148

D

100

0.00

100

QC

Quality Control

Memo

0.00

INSPECT RA 111369 D4148-0410 X 2 B60894

KITS ARE SCRAP

GIVE TO SMALL FAB TO SCRAP

110

QC21- Final Inspection - Work Order Release

0.00

110

QC

Quality Control

Memo

0.00

~~DAS~~DAS
10
8.3

12/14/12

12/17/30

Picklist Print

Wednesday, July 25, 2012 2:33:03 PM

Page 1

Work Order ID: 88047

Parent Item: D4148-041

Parent Item Name: Crosstube Lug Assembly, Fwd

Start Date: 7/24/2012

Required Date: 7/25/2012

Start Qty: 2.00

Required Qty: 2.00

Comments: IPP Rev:A 10.06.24 new issue DD verf:EC
IPP Rev:B 10.07.22 as per revB DD verf:JLM
DD verf:EC
IPP Rev:C 10.10.29 as per revC
IPP REV:D 11.03.02 AS PER DWG REV.D DD VERF:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4148-041 Crosstube Lug Assembly, Fwd		Manufactured	No				Each	14.0000		2			

Location

ST468

85752

Loc Qty

14

14

Loc Code

I X 60894 MF 12-07-25

U 12-07-30

RA111369 D4148-041

B60894

Received @ Dart July 3rd, 2012
Inspected @ Dart July 6th, 2012

Customer: TRANS AERO HELICOPTERS
Customer Contact: DENNIS PEDERSON
Shipped from: CHEYENNE WY USA

Instructions for RA 111369 D4148-041 B60894

- SCRAP now at rev D
- Needs new work order to scrap

Time Estimate = 1 HOUR ONLY (QC)

Departments Required: QC to scrap

Pictures Attached = NO

**THIS INSTRUCTION SHEET MUST
BE ATTACHED TO THE
RESTOCKING WORK ORDER AT
ALL TIMES!!!!**